


ಕರ್ನಾಟಕ ವಿಧಾನ ಪರಿಷತ್ತು

ಚುಕ್ಕೆ ಗುರುತಿಲ್ಲದ ಪ್ರಶ್ನೆ ಸಂಖ್ಯೆ:	923
ಮಾನ್ಯ ಸದಸ್ಯರ ಹೆಸರು	ಶ್ರೀ ಎನ್. ರವಿಕುಮಾರ್ (ವಿಧಾನ ಸಭೆಯಿಂದ ಚುನಾಯಿತರಾದವರು)
ಉತ್ತರಿಸಬೇಕಾದ ದಿನಾಂಕ	18-12-2018
ಉತ್ತರಿಸಬೇಕಾದ ಸಚಿವರು	ಆರೋಗ್ಯ ಮತ್ತು ಕುಟುಂಬ ಕಲ್ಯಾಣ ಸಚಿವರು

ಕ್ರ. ಸಂ.	ಪ್ರಶ್ನೆಗಳು	ಉತ್ತರಗಳು
ಅ)	ರಾಜ್ಯದಲ್ಲಿರುವ ಎಕ್ಸ್-ರೇ ಕೇಂದ್ರಗಳ ಸಂಖ್ಯೆ ಎಷ್ಟು; (ಜಿಲ್ಲಾವಾರು ವರದಿ ನೀಡುವುದು)	ರಾಜ್ಯದಲ್ಲಿ ಕರ್ನಾಟಕ ಖಾಸಗಿ ವೈದ್ಯಕೀಯ ಅಧಿನಿಯಮ (ಕೆ.ಪಿ.ಎಂ.ಎ.) ಅಡಿ ನೋಂದಣಿಯಾದ ಒಟ್ಟು ಎಕ್ಸ್-ರೇ ಕೇಂದ್ರಗಳ ಸಂಖ್ಯೆ 3419 (ಜಿಲ್ಲಾವಾರು ಎಕ್ಸ್-ರೇ ಕೇಂದ್ರಗಳ ಪಟ್ಟಿಯನ್ನು ಅನುಬಂಧ-1 ರಲ್ಲಿ ನೀಡಲಾಗಿದೆ).
ಆ)	ಎಕ್ಸ್-ರೇ ಕೇಂದ್ರಗಳನ್ನು ಪ್ರಾರಂಭಿಸಲು ಬೇಕಾದ ಅರ್ಹತೆ ಮತ್ತು ಮೂಲಭೂತ ಸೌಕರ್ಯಗಳೇನು;	ವಿವರವನ್ನು ಅನುಬಂಧ-2 ರಲ್ಲಿ ನೀಡಲಾಗಿದೆ.
ಇ)	ಕಳೆದ ಎರಡು ವರ್ಷಗಳಲ್ಲಿ ಸಮರ್ಪಕವಾಗಿ ಕಾರ್ಯನಿರ್ವಹಿಸದಿರುವ ಎಷ್ಟು ಎಕ್ಸ್-ರೇ ಕೇಂದ್ರಗಳ ಮೇಲೆ ಕೇಸು ದಾಖಲು ಮಾಡಲಾಗಿದೆ; (ವಿವರ ನೀಡುವುದು)	ಬೆಂಗಳೂರು ಗ್ರಾಮಾಂತರ ಜಿಲ್ಲೆಯ ಹೋಸಕೋಟೆ ತಾಲ್ಲೂಕಿನ ಎರಡು ಎಕ್ಸ್-ರೇ ಕೇಂದ್ರಗಳು ನಿಯಮವನ್ನು ಪಾಲಿಸದ ಹಿನ್ನೆಲೆಯಲ್ಲಿ ಜಪ್ತಿಮಾಡಿ ನಿಯಮಾವಳಿಗಳನ್ನು ಸರಿಪಡಿಸಿದ ನಂತರ ಪರವಾನಿಗೆ ನೀಡಲಾಗಿದೆ.
ಈ)	ವಿವಿಧ ರೀತಿಯ ಎಕ್ಸ್-ರೇ ಗಳಿಗೆ ಸರ್ಕಾರ ನಿಗದಿಪಡಿಸಿರುವ ದರಕ್ಕಿಂತ ಹೆಚ್ಚು ದರನಿಗದಿಪಡಿಸಿದ ಎಷ್ಟು ಎಕ್ಸ್-ರೇ ಕೇಂದ್ರಗಳಿಗೆ ನೋಟಿಸ್ ನೀಡಲಾಗಿದೆ; ಎಷ್ಟು ಎಕ್ಸ್-ರೇ ಕೇಂದ್ರಗಳ ಪರವಾನಿಗೆ ರದ್ದುಗೊಳಿಸಲಾಗಿದೆ? (ಕಳೆದ 6 ತಿಂಗಳ ಜಿಲ್ಲಾವಾರು ವಿವರ ನೀಡುವುದು)	ವಿವಿಧ ರೀತಿಯ ಎಕ್ಸ್-ರೇಗಳಿಗೆ ಸರ್ಕಾರದಿಂದ ದರ ನಿಗದಿ ಪಡಿಸಿರುವುದಿಲ್ಲ. ದರಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ ಯಾವುದೇ ಎಕ್ಸ್-ರೇ ಕೇಂದ್ರಗಳಿಗೆ ನೋಟಿಸ್ ನೀಡಿರುವುದಿಲ್ಲ ಮತ್ತು ಪರವಾನಿಗೆ ರದ್ದು ಪಡಿಸಿರುವುದಿಲ್ಲ.

ಸಂಖ್ಯೆ: ಆಕುಕ 923 ಚು.ರ. 2018


 (ಶಿವಾನಂದ ಎನ್. ಪಾಟೀಲ್)
 ಆರೋಗ್ಯ ಮತ್ತು ಕುಟುಂಬ ಕಲ್ಯಾಣ ಸಚಿವರು

ಅನುಬಂಧ-1

Details of X-Ray facilities Registered under KPME act

Sl. No.	Name of the District	No. Of X-Ray facilities available in the District	No. of X-Ray facilities availed Licenses as per KPME Registration	No of X-ray facilities without KPME Registration	Action taken against facilities who have violated the KPME act in last two years	Remarks
1	Bangalore Rural	38	36	2	2	
2	Bangalore Urban	2050	2050	0	0	
3	Bagalkote	35	35	0	0	
4	Belgaum	53	53	0	0	
5	Bellary	37	37	0	0	
6	vijapur	11	11	0	0	
7	Bidar	12	12	0	0	
8	Chitradurga	37	37	0	0	
9	Chikkamagaluru	36	36	0	0	
10	Chikkaballapur	29	29	0	0	
11	Chamarajanagar	10	10	0	0	
12	Davanagere	22	22	0	0	
13	Dharwad	72	72	0	0	
14	Dakshina Kannada	124	124	0	0	
15	Gadag	24	24	0	0	
16	Kulbarga	109	109	0	0	
17	Haveri	72	72	0	0	
18	Hassan	45	45	0	0	
19	Kolar	62	62	0	0	
20	Kodagu	12	12	0	0	
21	Koppal	15	15	0	0	
22	Mandya	25	25	0	0	
23	Mysore	207	207	0	0	
24	Ramanagara	16	16	0	0	
25	Raichur	7	7	0	0	
26	Shimoga	26	26	0	0	
27	Tumkuru	88	88	0	0	
28	Udupi	118	118	0	0	
29	Uttara Kannada	3	3	0	0	
30	Yadgiri	24	24	0	0	
Total		3419	3417	2	2	

ಎಕ್ಸ್-ರೇ ಕೇಂದ್ರಗಳನ್ನು ಪ್ರಾರಂಭಿಸಲು ಬೇಕಾಗುವ ಅರ್ಹತೆ ಮತ್ತು ಮೂಲಭೂತ ಸೌಕರ್ಯಗಳು

1. Only AERB Type approved X-ray equipment shall be installed /used.
2. AERB registration certificate shall be displayed at prominent place near the X-ray room for public information.
3. Quality Assurance tests of the X-ray equipment is carried out periodically and after any maintenance and the records thereof are maintained.
4. Sufficient number of lead aprons (0.25 mm lead equivalent) is available for use with fixed and mobile X-ray equipment.
5. Lead aprons shall be stored either on a hanger or on a flat surface without crumpling.
6. Consistency of lead aprons shall be checked once in two years. Qualitative check can be done by taking radiograph of lead aprons.
7. The operators are instructed on all the requirements of radiation safety.
8. Charts of standard exposure parameters to achieve good image quality should be prepared for paediatric and adult patients separately and displayed at a prominent location such as control console.
9. TLD badges are provided to all the operators and workers involved during X-ray examination.
10. During non-working hours, TLD cards must be stored along with Control TLD card outside the X-ray room (in a radiation free area).
11. The owner shall ensure that the operator of the X-ray equipment is well conversant with clinical requirements of the examinations. Chest stand should always be provided with X-ray equipment for chest radiography.
12. Routine maintenance of the Radiography equipment is carried out. Particularly, it should be ensured that the field light (collimator bulb) is always functional.
13. Radiation symbol and warning placards in local languages are placed outside the X-ray room door.
14. The chest stand and the control console should always be placed opposite to each other. If this is not possible, at least a partition wall with viewing window should be made between the control console and the chest stand.
15. Permanent occupancy of staff behind the chest stand wall (for e.g. Doctors, Receptionists or helpers) should be avoided.